

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Clearview Waste Management Landfill	Facility Location ID :	110002225976
Assessment Date :	8/28/2010	Incident Name :	BP Spill
Physical Location :	2253 Mudline Road		
City, State :	Lake , MS	County :	Scott

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management; Custom Ecology, Inc.
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments : During this operational period Ken Feely, Waste Disposal Technical Specialist, conducted a site monitoring visit from 0935 hours to 1125 hours at the Waste Management Clearview landfill. Jason Bridges (MDEQ) was invited to participate in the visit but could not attend. Jim Johnston, Waste Management Landfill Operations Manager, said the landfill is averaging about 10 loads of BP waste per day. The landfill first received BP waste on 8/19. All waste received to date has been classified as oil contaminated debris. During the visit, the offloading of two BP waste loads was observed. One load was a partially full roll-off containing oily hard boom. The other load (full) was primarily oily PPE and a small amount of absorbent boom packaged in plastic bags.	